

Work Order Bid (ID)

WORK TO BE PERFORMED IN ACCORDANCE WITH 2011 TENNESSEE WEATHERIZATION FIELD GUIDE and ANY LOCAL CODES. QUESTIONS SHOULD BE DIRECTED TO EAST TENNESSEE RESOURCE AGENCY - WEATHERIZATION DEPT.

WORK ORDER INFORMATION

Work Order Name: WO/60006EA7383/1
Work Order Type: Weatherization
Audit Name: 60006EA7383AUDIT

CLIENT INFORMATION

Client ID: 60006EA7383

AGENCY INFORMATION

Agency:East Tennessee Human Resource AgencyAgency Phone:(865) 691-2551Address:9111 Cross Park Drive, Suite D100Fax:(865) 531-7216

Knoxville, TN 37923 *Email Address:*

Company Name & License Number:	
Contractor's Signature:	

COMMENT

SITE BUILT 1966 APPROX. 1400 SQ. FT. FUEL ELECTRIC EXTERIOR BRICK AUDIT PERFORMED 6/22/2011

	EPLACE DOOR @ BASEN			Componer	nts		1	Inspecte
Comment DOO	R GOING TO BASEMENT LACED WITH METAL DOO	IS HOLLO		OD AND N	EEDS TO) BE		
		,	,	Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified	Misc Material	Each	1					
Other Detail								
			Measur	e Sub Total:] ,	Sub Total:	
Field Notes:								
Measure 2 Ir	filtration Redctn TIC 1 RETURN AND 9 SUF	PPLY DUC	TS.	Componer				nspecte
Measure 2 In	TIC 1 RETURN AND 9 SUF			Estimated	1		Actual	
Measure 2 Ir Comment MAS	TIC 1 RETURN AND 9 SUF	Units	Qty	•		Qty		Inspecte
Measure 2 In	TIC 1 RETURN AND 9 SUF			Estimated	1	Oty .	Actual	
Measure 2 Ir Comment MAS	TIC 1 RETURN AND 9 SUF	Units	Qty	Estimated	1	Qty	Actual	
Measure 2 Ir Comment MAS # Material / Labor 10 Miscellaneous	TIC 1 RETURN AND 9 SUF	Units	Qty	Estimated	1	Qty	Actual	
Measure 2 Ir Comment MAS # Material / Labor 10 Miscellaneous	TIC 1 RETURN AND 9 SUF	Units Each	Qty 1	Estimated Unit Cost	1		Actual Unit Cost	
Measure 2 Ir Comment MAS # Material / Labor 10 Miscellaneous	TIC 1 RETURN AND 9 SUF	Units Each	Qty 1	Estimated	1		Actual	

		H Pipe Insulation	Notor Line		Componen	ts			Inspected
C	<i>comment</i> 6 Ln. Ft.	. @ Each Hot and Cold V	vater Line		Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	DHW Pipe Insulation	Each	1					
(Other Detail						1		
] []		
L				Moseur	re Sub Total:] []	Sub Total:	
ſ	Field Notes:			INCASUI	e oub rotar.]		
	Comment Contract	tor to discuss with home	owner and	deterr	Componen		nt		Inspected
	places to	o install CFL's.			Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Lighting	Compact Fl 26 Watt	Each Lamp	4					
2	Labor	Compact Fl 26 Watt	Each Lamp	4					
(Other Detail								
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								

Measure 5 DW Comment	H Tank Insulation			Componen				Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Hot Water Equipr	m DHW Tank Insulation	Each	1					
2 Labor	DHW Tank Insulation	Each	1					
Other Detail			1					
]	Sub Total:	
			weasur	e Sub Total:		'	Sub Total.	
Measure 6 Flo	or Ins. R-19			Component Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1400		70.01	u.,		70.07
2 Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	1400					
Other Detail	7							
			Measur	e Sub Total:] ,	Sub Total:	
Field Notes:								

1 Insulation Attic Insulation - Blown Cellulose - R-30 2 Labor Attic Insulation - Blown Cellulose - R-30 3 Miscellaneous Su Added Misc Cost Each 1	Measure 7 Attic	Ins. R-30			Componen	<i>ts</i> A1		I	nspecte
# Material / Labor Description / Comment Units Oty Unit Cost Total Oty Unit Cost Total I Insulation Attic Insulation - Blown Cellulose - R-30 2 Labor Attic Insulation - Blown Cellulose - R-30 3 Miscellaneous Su Added Misc Cost Each 1	INSTAL	L ATTIC ACCESS LID A			0" INCHES (660 Sq.	In.)		
1 Insulation Attic Insulation - Blown Cellulose - R-30 2 Labor Attic Insulation - Blown Cellulose - R-30 3 Miscellaneous Su Added Misc Cost Each 1					Estimated			Actual	
Cellulose - R-30 Attic Insulation - Blown Cellulose - R-30 3 Miscellaneous Su Added Misc Cost Each 1	# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Cellulose - R-30 3 Miscellaneous Su Added Misc Cost Each 1	1 Insulation		SqFt	1400					
Measure 8 Fix Improper Venting Kitchen Exhaust Components Fan Comment # Material / Labor Description / Comment Units Qty Unit Cost Total Qty Unit Cost Total Measure for a list of materials. Other Detail Measure Sub Total: Sub Total: Inspects Actual Actual Actual Other Detail Measure Sub Total: Sub Total: Sub Total:	2 Labor		SqFt	1400					
Measure Sub Total: Sub Total: Sub Total:	3 Miscellaneous Su	Added Misc Cost	Each	1					
Field Notes: Measure 8 Fix Improper Venting Kitchen Exhaust Components Inspects	Other Detail								
Field Notes: Measure 8 Fix Improper Venting Kitchen Exhaust Components Inspects									
Field Notes: Measure 8 Fix Improper Venting Kitchen Exhaust Components Inspects									
Measure 8 Fix Improper Venting Kitchen Exhaust Components Fan Comment # Material / Labor Description / Comment Units Qty Unit Cost Total Qty Unit Cost Total Unspecified See the User Defined Measure for a list of materials. Other Detail Measure Sub Total: Sub Total:				Measur	e Sub Total:			Sub Total:	
# Material / Labor Description / Comment Units Qty Unit Cost Total Qty Unit Cost Total Units Qty Unit Cost Total Qty Unit Cost Total Other Detail Measure Sub Total: Sub Total:	Fan	mproper Venting Kitch	en Exhau	st	Componen	ts		I	nspecte
Unspecified See the User Defined Measure for a list of materials. Other Detail Measure Sub Total: Sub Total:	Comment				Estimated			Actual	
Measure for a list of materials. Other Detail Measure Sub Total: Sub Total:	# Material / Labor	Description / Comment	Units	Qty			Qty		Total
Measure Sub Total: Sub Total:	10 Unspecified		Each	1					
		materials.							
	Other Detail	materials.							
	Other Detail	materials.							
Field Notes:	Other Detail	materials.							
	Other Detail	materials.		Measur	e Sub Total:			Sub Total:	

Measure 9 Ir Comment	nstall Bathroom Exhaust F	-an		Componen	ts			Inspecte
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Unspecified	See the User Defined Measure for a list of materials.	Each	1					
Other Detail						1		
			Measur	e Sub Total:]	Sub Total:	
()	ractice Lead Safe Weathe Attic Access)	rization		Componen				Inspecte
(<i>P</i> Comment	Attic Access)			Estimated			Actual	
(<i>J</i> Comment # Material / Labor	Attic Access)	units Each	<i>Qty</i> 1	·		Qty		Inspecte
(<i>J</i> Comment # Material / Labor	Description / Comment See the User Defined Measure for a list of	Units		Estimated		Qty	Actual	
Comment # Material / Labor Unspecified	Description / Comment See the User Defined Measure for a list of	Units		Estimated		Qty	Actual	
Comment # Material / Labor Unspecified	Description / Comment See the User Defined Measure for a list of	Units		Estimated		Qty	Actual	
Comment # Material / Labor Unspecified	Description / Comment See the User Defined Measure for a list of	Units Each	1	Estimated			Actual	

	Measure 11 PressureRelief Piping Needed			Components					Inspected	
C	Comment									
				Estimated	Actual					
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Health and Safety	Pressure relief piping	Each	1						
2	Labor	Labor	Each	1						
	Other Detail									
L										
			Measure Sub Total: Sub Total:							
	Field Notes:									
			Work Or	der Gra	nd Total:		Gran	d Total:		